

## APPROVED DOCUMENT CHANGE CONTROL FORM

Date

Do not use blue ink. Type, or print in black

1/23/91

Document Number & Title

DOE-RL, Rev. 1, "Remedial Investigation/Feasibility Study Work Plan for the 200-BP-1 Operable Unit Date Document Last Issued

Hanford Site, Richland, WA

March 1990

Originator

M. A. Buckmaster 200-BP-1 RI Coordinator

Phone

376-1792

## Description of Change

Add the words "or until it has been determined that the Elephant Mountain Basalt Member is absent." To the end of the 5th sentence of the 1st paragraph, on SAP/FSP-33 and to the 2nd sentence of the first full paragraph on WP-150.



Note: Include affected page number

## Justification and Impacts of Change

The 200-BP-1 WP and SAP does not provide specific instructions for completing an unconfined groundwater monitoring well when an erosional window in the Elephant Mountain Basalt Member is encountered. Well 699-55-55 was drilled through an erosional window before drilling was terminated due to a bent casing at 310 ft. below ground surface.

J. K. Erickson 1-25-91

DOE UNIT MANAGER

DATE

D. R. Sherwood

1/29/91

LEAD REGULATORY UNIT MANAGER

DATE

Per Action Plan for Implementation of the Hanford Consent Order and Compliance Agreement, Section 9.3